

Known Issues with the SmartWORKS IPX

Issue Date: 05/25/07

Issue

When running 3.9 or lower after a period of time the SmartWORKS IPX board will return MT_TIMEOUT with all function calls and stops event reporting. The SmartWORKS IPX board may also eventually cause the host system to freeze.

Products Affected

All SmartWORKS IPX boards running SmartWORKS 3.9 or lower.

Resolution

AudioCodes has provided a point release to resolve these issues. All customers are required to use SmartWORKS 3.9.1 or greater.